



## PROFILE OF REPORTS

File No:081200\_0\_000  
 MASTER CONTRACT: 179123  
 Submitter: 4557667  
 Otis Instruments, Incorporated  
 2200 East Villa Maria  
 Bryan, TX 77802  
 USA  
 Attention: Mr. Wayne Carroll  
 Tel: (409) 823-1530  
 FAX: (409) 823-8990

Date: **March 9, 2010**  
 Replaces: **December 10, 2009**

Factories			Inspection
Contact No	Name & Address		Office: File No / Factory Contract No
4557667 (F1)	Otis Instruments, Incorporated 2200 East Villa Maria Bryan, TX 77802		CSA 81200 / 179124 Dallas, TX
Report	Project	Contact No	Subject
-1			November 1, 1990: PART A - Hydrogen Sulfide Gas Detection System Model OI-610, for Class I, Groups C and D Hazardous Locations. PART B - Hydrogen Sulfide Gas Detection Sensor/Enclosure Assembly, Model OI-630, for Class I, Groups C and D Hazardous Locations.
	-2		NTRL/C, July 5, 1993 - Update to Report LR 81200-1 to cover Model OI-240HS sensor for Class I, Groups C and D hazardous locations.
-5			March 29, 1996 - Combustible Gas Sensor Model OI-120HS.
-	-	-	November 30, 2001 - Change in Company Address and Factory.
1577613			July 20, 2004 - Delisting of Models - Hydrogen Sulfide Gas Detection System Model OI-610, Hydrogen Sulfide Gas Detection Sensor/Enclosure Assembly, Model OI-630 Also, add the letter S to Model OI-240H(omitted in error).
-	-	F1	May 15, 2007 - CSC - Change Company (Submittor's) & Factory Location from: 2244 Westwood Main

Bryan, TX 77807

To:

2200 East Villa Maria

Bryan, TX 77802

1905007		F1	May 29, 2007 - Evaluation of Model OI-254 Sensor for use in Class I Div 1 Groups C and D (CSA C22.2 No. 0-91, CSA C22.2 No. 30-1986, CSA C22.2 No. 142-M1987 - Process Control Equipment UL 508 17th edition, UL 1203 4th ed). Report in Edmonton.
Ed. 2	2248557	F1	December 10, 2009 – Update report 1905007 to include a list of acceptable sensors for use in the device.
2082495			March 12, 2009 – Report closed incomplete.
Ed. 1			
2082503			March 12, 2009 – Report closed incomplete.
2155058			September 24, 2009 – Report 2155058 closed incomplete due to major scope change.
2155059			September 24, 2009 – Report 2155059 closed incomplete due to major scope change.
2238531	-	F1	March 9, 2010 – First Report 2238531 certification to include Class I, Division 1, Group C and D; Ex d IIB; Zone I AEx d IIB for Toxic Gas Detector to include Models OI-5900, OI-6000, OI-6900 and OI-7000. Applicable Requirements: C22.2 0.4:2004, CSA C22.2 No. 30-M1986, CSA C22.2 No. 142-M1987, C22.2 No. E60079-0:07, C22.2 No. E60079-1:04 UL 508 17th edition, FM 3600:1998, FM 3615:2006, UL 60079-0 4 <sup>th</sup> Ed., UL 60079-1 5 <sup>th</sup> Ed.
Ed. 1			

/mr